

INFORMATION REPORT

CD NO. 25X1A

Approved For Release 2002/07/12 : CIA-RDP80-00810A000700200005-7

COUNTRY **East Germany** DATE DISTR. **10 April 1953**

SUBJECT **Railroad Tank Cars Operating through East German Border Stations** NO. OF PAGES **4**

PLACE ACQUIRED 25X1C NO. OF ENCLS. (LISTED BELOW) **25X1A**

DATE OF INFO. SUPPLEMENT TO REPORT NO.

25X1X

25X1

25X1

Berlin, the following numbers of tank cars operated through the border stations mentioned from 27 January through 4 February 1953:

Date in January	Number of Cars	Westbound			Via	Number of Cars	Eastbound		
		Load	From	To			Load	From	To
27	16	empty	Brest Litovsk	Merseburg	Frankfurt/Oder				
	3	military goods	"	Velten					
	1	toluol oil	"	Leipzig-Leutzsch					
	5	empty	"	Boehlen					
	1	"	"	"					
	30	"	Stettin	Grosskorbetha	Forst				
					Bad Schandau	41	empty	Krumpa	Austria
	43	crude oil	Austria	Krumpa	Bad Brambach	49 40	empty "	" Grosskorbetha	" "
28	1	empty	Brest Litovsk	Merseburg	Frankfurt/Oder	1 2 1	gas wood alcohol	Spandau Grosskorbetha Merseburg	Reppen Brest Litovsk "
	12	empty	Poland	Ruhland	Horka	35	Diesel oil	Troeg-litz	Poland

193

DIRECT DISSEMINATION

25X1A

Approved For Release 2002/07/12 : CIA-RDP80-00810A000700200005-7

25X1X

SECRET/CONTROL - U.S. OFFICIALS ONLY

-2-

				Forst	20	Diesel oil	Troeglitz	Poland
				Scheune	57	"	"	"
36	crude oil	Austria	Krumpa	Bad Schandau				
6	"	"	Grosskor-betha	Bad Brambach	81	empty	Leuna	Austria
29	1	empty	Brest Litovsk	Grosskor-betha	Frankfurt/Oder			
4	"	"	Merseburg					
19	"	"	Grosskor-betha					
1	toluol oil	"	Rosslau					
6	military goods	"	Velten 1					
6	empty	Poland	Ruhland	Horka	36	Diesel oil	Troeglitz	Poland
8	"	"	"	Forst	31	gasoline	Grosskor-betha	"
36	crude oil	Austria	Grosskor-betha	Bad Brambach	21	empty	Grosskor-betha	Austria
19	"	"	Krumpa	Bad Schandau	2	gasoline	Gruenau	Hungary
30				Frankfurt/Oder	37	"	Grosskor-betha	Poland
					18	"	Boehlen	Zhabinka
30	empty	Poland	Grosskor-betha	Forst	43	tar oil	Troeglitz	Poland
				Horka	13	"	"	"
47	crude oil	Austria	"	Bad Schandau	57	empty	Grosskor-betha	Austria
23	"	"	Krumpa	Bad Brambach	19	"	Krumpa	"
31	5	empty	Brest Litovsk	Merseburg	Frankfurt/Oder	7	wood alcohol	Grosskor-betha
						13	paraldehyde	Merseburg
23	"	Poland	Troeglitz	Horka	37	Diesel oil	Troeglitz	Poland
17	"	"	Grosskor-betha	Forst	29	"	"	"

SECRET/CONTROL - U.S. OFFICIALS ONLY

SECRET/CONTROL - U.S. OFFICIALS ONLY

-3-

25X1X


32	crude oil	Austria	Grosskor- betha	Bad Schandau	18	empty	Grosskor- betha	Austria
25	"	"	Krumpa	Bad Brambach	12	"	Krumpa	"
February								
1	No shipments reported							
2	7	military goods	Brest Litovsk	Velten 1	Frankfurt/Oder	48	gasoline	Grosskor- Poland
	13	empty	"	Grosskor- betha			betha	
	15	"	"	Boehlen				
	3	toluol oil	"	Schoenebeck				
	30	empty	Poland	Troeglitz	Forst	23	Diesel oil	Troeglitz Poland
				Scheune		32	"	" Stettin
	48	crude oil	Austria	Grosskor- betha	Bad Schandau	43	empty	Grosskor- Austria
	23	"	"	Krumpa	Bad Brambach			betha
3	7	empty	Brest Litovsk	Grosskor- betha	Frankfurt/Oder			
	10	"	"	Merseburg				
				Forst		1	gasoline	Grosskor- Poland
							betha	
	3	crude oil	Austria	Poland	Bad Schandau			
	46	"	"	Grosskor- betha	Bad Brambach	79	empty	" Austria
4	4	empty	Brest Litovsk	Merseburg	Frankfurt/Oder	23	gasoline	Boehlen Zhabinka
	47	"	Poland	Troeglitz	Horka			
				Forst		1	"	Grosskor- Poland
							betha	
	26	"	Stettin	Grosskor- betha	Scheune			
	14	crude oil	Austria	Mockethal	Bad Schandau			
	2	"	"	Krumpa				
	67	"	"	Grosskor- betha	Bad Brambach	89	empty	Krumpa Austria
						41	"	Grosskor- "
							betha	

SECRET/CONTROL - U.S. OFFICIALS ONLY



25X1X

SECRET/CONTROL - U.S. OFFICIALS ONLY

-4-



25X1A

1.  Comment. A large fuel depot of the GCFG is located in Velten.
2.  Comment. Tank car traffic throughout the reported period was normal.

SECRET/CONTROL - U.S. OFFICIALS ONLY